# 3145 MEN'S FREETOWN POLO

# **SIZES S-5XL**

- :: 100% cotton slub knit (5.46 oz/yd², 185GSM)
- :: Garment dyed then old washed to create a soft, textured hand feel



# **BACK VIEW**





### **COMFORT & CONVENIENCE**

- :: Great textures of slubknit with woven chambray trim detailing on the inside placket, collar and side vents for a superior look and feel
- :: Garment dyed then old washed to create a soft, textured hand feel
- :: Self-fabric collar with interfacing for stability

## **FABRIC**

100% cotton slub knit (5.46 oz/yd², 185GSM)

#### **SIZES**

Sizes S-5XL

#### **COLORS**

040 Navy, 201 Charcoal, 010 Black, 080 White, 371 Bay

### **GARMENT CARE**

Machine wash cold with like colors. Gentle cycle. Only non-chlorine bleach when needed. Tubmble dry low. Remove promptly. Color iron if needed.

#### **DECORATION RECOMMENDATIONS**

Embroidery: Ballpoint 70/10 needle. 2 Cutaway (no show mesh) stacked and rotated into a multipoint star. Topical Solvent recommended if small letters are included.

Heat Transfer: Max heat recommended is 315°F

Screen Printing: Automatic printing process is recommended. Maximum number of colors recommended is 4. Plastisol ink recommended for both white and dark ink colors. Catalyst recommended. Dryer temperature should not exceed 315°F with a belt speed of 22.

010 BLACK

040 NAVY

080 WHITE

201 CHARCOAL

371 BAY



FREETOWN POLO MEN'S 3145	S	М	L	XL	XXL	3XL	4XL	5XL	TOLERANCE
BODY LENGTH measure from neck (CB neck)	27	28	29	29¾	30½	311/4	32	32½	1/2 +/-
ACCROSS SHOULDER	171/2	18	181/2	191/2	201/2	21½	221/2	231/2	1/2 +/-
CHEST WIDTH measure 1 inch below armhole	21	22	23	25	27	29	31	33	1/2 +/-
BOTTOM OPENING WIDTH RELAXED 1/2	20	21	22	24	26	28	30	32	1/2 +/-
SLEEVE LENGTH measure from CB	191/2	19%	201/4	20%	21½	221/8	225/8	231/8	1/4 +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED

